




STAMP Tag Deploying Form

. Tagged by: Tarun + Patrick King		
. Tag Number(s) (####): MD 00 82		
. Date: 3/29/24 Time: 2:5/ am (pm)		
Tide level: High Medium Low-2/2/2 Level. Name of wreck (if known): Unknown		
Float Uncovered Other		
Main Material of Construction: What is the wreckage material?	Skip the following questions if not wooden wreckage	
✓ Wood ☐ Steel ☐ Iron ☐ Fiberglass	If the wreckage is wood, does it appear to be:	
Check the following boxes if these details are present on the wreckage:	☐ Hand hewn ☐ Machine Cut☐ Both ☐ Other	
Treenails	Look at the images on the	
Round Spikes Other	instruction sheet and give your best guess on what part of the	
Check the following boxes if the materials are present on the wreckage:	shipwreck you believe you found. Can't be determined.	
Ø Wood ☐ Iron ☐ Copper ☐ Steel ☐		


Completely exposed Partially exposed New Directions: 22ft from June for a line	avily deteriorated as wreckage is: arly covered
son more wheter e line	
10 Fotimeted V	4
10. Estimated distance from the high tide line:	
below (ft) Wabove 39	(ft)
beach zone behind primary dune	THE STATE OF THE S
11.GPS coordinates:	
Latitude: 38°/2'44"N Longitude: 75°8	2/= 3 " /
12. Length/Width/Thickness of timber:	03 W
Length: 47" (_) Width: 10" () Thickness	0"
Orientation: Not by a described to 2000 a	. 8
Orientation: perpendicular to o cea Diameter of wooden fasteners: 1"	
Distance between 2 fasteners:	
13. Pictures: 7 photos - Fators, length, ent	(Name/Id#)
Mbon82	(**************************************
	(continue on back
14. Comments: No wornholes, 1 to the or una	Jerneath very
deteriorated.	
	W.



Overview





Beneath deteriorated end



Opposite end to previous image (Left)

End of timber with treenails. Pattern of fasteners is on a 4" diagonal (Below)





Details of treenails

